

Map ID
 Direction
 Distance
 Elevation

MAP FINDINGS

EDR ID Number
 EPA ID Number

GY1002
East
> 1
1.314 mi.
6940 ft.

TM 1963
NEPTUNE AVE & EAST 14TH
BROOKLYN, NY

NY Spills **S104788218**
 N/A

Site 2 of 13 in cluster GY

Relative:
Higher

Actual:
6 ft.

SPILLS:

Name: TM 1963
 Address: NEPTUNE AVE & EAST 14TH
 City,State,Zip: BROOKLYN, NY
 Spill Number/Closed Date: 0005573 / 2003-06-02
 Facility ID: 0005573
 Facility Type: ER
 DER Facility ID: 146644
 Site ID: 174328
 DEC Region: 2
 Spill Cause: Unknown
 Spill Class: C4
 SWIS: 2401
 Spill Date: 2000-08-09
 Investigator: JHOCONNE
 Referred To: Not reported
 Reported to Dept: 2000-08-09
 CID: 252
 Water Affected: Not reported
 Spill Source: Commercial/Industrial
 Spill Notifier: Affected Persons
 Cleanup Ceased: Not reported
 Cleanup Meets Std: False
 Last Inspection: Not reported
 Recommended Penalty: False
 UST Trust: False
 Remediation Phase: 0
 Date Entered In Computer: 2000-08-09
 Spill Record Last Update: 2003-06-02
 Spiller Name: UNKNOWN
 Spiller Company: Unknown
 Spiller Address: UNKNOWN
 Spiller Company: 999
 Contact Name: TONY LOPEZ
 DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL E2MIS 132794 8/9/00--1440HRS NIGRO I&A REPORTS FOUND APPROX 1-PINT OF UNKNOWN OIL ON 300 GALLONS OF WATER IN TM1963.IT APPEARS TO BE CONTAINED AT THIS TIME NO SEWERS OR WATERWAYS EFFECTED 1-SAMPLE TAKEN TAG#06433 PLACED.RECORDS SHOW 9-PPM .CREW WILL PRESSURE TEST UNIT .CLEANUP PENDING TEST RESULTS. 1600HRS--O.S. A.WALKER REPORTS PRESSURE TEST HELD TM-1963 NOT LEAKING 1950HRS O.S.A.WALKER REPORTS VEHICLE#60532 WAS CONTAMINATED IN THE CLEANUP OF TM-1963,REMOVED ALL DEBRIS AND LIQUIDS ,MADE WORKABLE TAG REMAINS. Update - 8/9/00 2000hrs - Chem lab results recd lsn# 00-07688 <1ppm 8/14/00--1930hrs QUIJIJE ENVIR.OPPS REPORTS CLEANUP COMPLETED TAG#6433 REMOVED UPDATE 1/27/03 ALL CLEAN UPS IN 2000 WERE PERFORMED BY DOUBLE WASHING STRUCTURE WITH SLIX OR BIO - GEN 760 AND THE LEAST... SINCE THIS WAS A < 1 PPM CLEAN UP THE CLEAN UP WAS MOST LIKELY PERFORMED BY DOUBLE WASHING STRUCTURE WITH SLIX OR BIO GEN 760 ...EV"
 Remarks: "APPROX 1 PINT OF UNK PETROLEUM IS ON 300 GALLONS OF WATER-SAMPLE TAKEN-CLEANUP PENDING RESULTS- CON ED #132794."

All Materials:
 Site ID:

174328

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Operable Unit ID: 828136
Operable Unit: 01
Material ID: 546723
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported